

+	+	M05-Klemmenplan Kommandopult	
		1	+KOP×44
+	+	M06-Klemmenplan Schaltschrank 1	
		1	+SH1×2
		2	+SH1×2
		3	+SH1×9
		4	+SH1×9
		5	+SH1×12
+	+	M07-Klemmenplan Schaltschrank 2	
		1	+SH2-2×0V
		2	+SH2-2×0V
		3	+SH2-2×24V
		4	+SH2-2×PE
		5	+SH2×3
+	+	M08-Klemmenplan Maschine	
		1	+MGE×31
		2	+MGE×32
		3	+MGE×33
		4	+MGE×34
		5	+MGE×51
		6	+MGE×52
		7	+MGE×53